



1235 Gorham Street Unit #15 , Newmarket ,ON L3Y 8Y5

Jim Murray

96 Undercliff

RE: HVAC Replacement Quote

Donair is pleased to provide a quote to replace HVAC equipment at the above location. The cost to complete the replacement will \$8,050 plus HST.

Includes: York 2-stage 96% eff furnace

: York 4-ton condensing unit with new evaporator coil.

: new 636 vent pipes

: new refrigerant lines

Removal of all old equipment and all necessary duct connections.

If you should have any concerns, please fill free to give us a call.

Thanks

Mitch Short